



Clearcreek Road Department

Monthly Report

April 2025

On April 1, Road crews inspected every culvert pipe in the township before significant rainfall began. During the subsequent storms, the estimated rainfall was five to nine inches over four days, washing out areas of roadway. The berm on Weidner Road washed away at a length of 150 feet, leaving a two-foot drop by the edge of the road. Each culvert pipe in the area overflowed, accumulating floodwater downstream and creating a drop-off as soil and road material washed away. Crews hauled six loads of rip rap to repair the damage. Following the storms and repairs on Weidner Road, crews re-inspected culverts and roadways throughout the township and made necessary repairs.



With warmer weather arriving, crews repaired several lawns damaged from winter plowing. Throughout April, crews also dug ten ditches and installed two driveway pipes.

With assistance from the Parks Department, crews installed sod around the salt bin. This work required ten skids of sod, and crews completed the work in one day.

Road Crews added 234 tons of milled asphalt to the driveway leading to Hoffmann Reserve. Crews also cleaned the ditch beside the service road to prevent water overflow.



Road Maintenance Crews ended the month repairing a catch basin in Crown Point. The heavy rainfall washed away portions of the catch basin wall, causing the top to collapse six inches into the basin. Crews blocked the walls and fabricated a new top using five yards of concrete and two tons of asphalt.

