



Clearcreek Road Department

Monthly Report

July 2026

North Bunnell Hill Road Drainage Improvements

During the first week of July, North Bunnell Hill Road was closed to complete drainage improvements from the curve to Crown Point Meadows. Due to the unusually heavy rainfall this year, this area has experienced recurring flooding and generated numerous complaints.

The crew widened and regraded the roadside ditch to increase capacity and installed riprap upstream of the catch basin to reduce water velocity and erosion. The ditch through the curve was also regraded, and the excavated material was used to repair washouts between the field and the ditch. Since completion, several heavy rain events have occurred, and the improvements have successfully prevented roadway flooding.

North Bunnell Hill Road Repair

While the road was closed, the crew repaired a soft spot in the curve. What began as an anticipated 5-ton asphalt repair became a 51-ton repair after excavation revealed the roadway had little to no base beneath the pavement due to previous widening projects. The repair restored the roadway's structural integrity.

Mastic Patching Program

The crew completed mastic patching throughout the Crown Point Meadows and Foxdale Farms subdivisions over a three-week period, using approximately 13 skids (37,440 pounds) of mastic material. This work is part of the Township's pavement preservation program and prepares these roads for the 2027 Cape Seal Program.

Storm Cleanup

Throughout July, crews responded to several storm events by clearing debris, addressing drainage issues, and restoring roadway conditions to ensure safe travel.

Summary

July's work focused on improving drainage, completing necessary roadway repairs, advancing the Township's pavement preservation program, and responding to storm damage. These efforts have improved roadway conditions and helped reduce future maintenance needs.



N Bunnell Hill Prior to Improvements



Completed drainage improvements on N Bunnell Hill Rd



N Bunnell Hill ditch repair



Repaired soft spot in the curve on N Bunnell Hill Rd

