



View looking west from side yard.



View looking northeast from southern property line.

**3657 Mary Ann Dr
Staff Photos November 13, 2025
25-BZA-001 Exhibit: 20A**



View looking north from southern property line.



View looking south from pool.

**3657 Mary Ann Dr
Staff Photos November 13, 2025
25-BZA-001 Exhibit: 20B**



View looking east, note septic tank lids.



View looking south, blue arrow identifies fence.

**3657 Mary Ann Dr
Staff Photos November 13, 2025
25-BZA-001 Exhibit: 20C**



View looking west from pool.



View looking northwest from septic tank lids.

**3657 Mary Ann Dr
Staff Photos November 13, 2025
25-BZA-001 Exhibit: 20D**



View looking east from septic tank lids.



View looking south. Note ornamental grass no longer a buffer to deck.

**3657 Mary Ann Dr
Staff Photos November 13, 2025
25-BZA-001 Exhibit: 20E**



View looking northeast from septic tank lids.



View looking northwest from septic tank lids.

**3657 Mary Ann Dr
Staff Photos November 13, 2025
25-BZA-001 Exhibit: 20F**